

Injectronics

TECHNICAL BULLETIN

LEXUS INSTRUMENT DISPLAY

#T0141

Customer Complaint:

There is nothing more frustrating than when technology doesn't work properly. That's what Injectronics technicians have recently been hearing from our customers. Enquiries relating to Lexus information displays have increased recently causing frustration for the driver.

The vehicle presents with no issues relating to Audio, DVD, Bluetooth, reversing camera, etc. The physical buttons on either side of the screen are operating as they should, allowing the driver to scroll between different screens but the driver is experiencing the following:

- Screen does not respond to touch
- Screen is blank
- Screen is cracked or broken

Affected vehicles:

- Lexus IS250 GSE20R 2.5L (2005-on)
- Lexus IS250C GSE20R 2.5L (2009-2015)
- Lexus IS250 GSE25R 2.5L (2005-2013)
- Lexus IS350 GSE21R 3.5L (2005-on)

Diagnosis:

If you experience a vehicle presenting with a blank screen or the screen is failing to respond to touch, the unit should be removed and all connections to the back of the unit should be tested for correct fitment.

Once no fault is found with the connections, it can be determined that the unit is faulty. This is where Injectronics can offer a solution. Injectronics can provide a prompt test and repair service of the customers own unit. This will allow the customer to then refit the drivers original unit directly back into the vehicle saving time and money. It will also remove the need for any further programming to the car should a second hand unit be fitted.

Repair Part number: ICCLEXREP

OE Part numbers:

- 8611153040
- 8643153331
- 4622001433
- 4123004791



ICCLEXREP

injectronics.com.au

This information has been offered with the intent to provide a resource of reliable information; however no warranty (express or implied) is made as to the accuracy or completeness. No liability is assumed by Injectronics for damage or loss resulting from reliance on this information or process.